

F I G. 1




FIG. 2A




FIG. 2B




FIG. 3






FIG. 4


four step (reading out inspection signals)




F I G. 5A




F I G. 5B




F I G. 5C




F I G. 6




F I G. 7A




F I G. 7B




F I G. 7C



F I G. 7D



F I G. 7E



F I G. 7F




FIG. 8A





FIG. 8B



F I G. 9




FIG. 10A







FIG. 10B




F I G. 11



F I G. 12A



F I G. 12B



F I G. 12C




FIG. 13A PRIOR ART





FIG. 13B



F I G. 14

